The information included in this report detail the laboratory results from water samples taken from locations in the school district building. Any sample results with a reading of greater than **0.015** signifies a lead content beyond the NYS approved limit for school districts. We will be working to diagnose the problem areas and will be taking steps to replace piping and / or fixtures in the problem areas. This will be a long process in some cases. We are also required to take follow-up samples once we think an area has been remediated. The lab testing is taking about 3-4 weeks to process following the collection. This report will be updated as areas are addressed.

If you have any specific questions during the process, please don't hesitate to contact me directly. Thank you for your patience and understanding during the process.

Chad C. Groff
Superintendent of Schools
607-545-6421

Site ID / Location of Sample:	Rm 207 Bac	k Sink	Date:	9/20/2016		
LSL ID#	Sample ults:	0.013				
Remediation Plan f	Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Rm 207 Fron	nt Sink	Date:	9/20/2016		
LSL ID #	> 002	Original	Sample	0.051		
Remediation Plan f	or Outlet / Tap:	Resi	ults:			
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
Sample Results Afte	Sample Results After Remediation: Date:					

Site ID / Location of Sample:	2nd Floor Hallway F	ountain	Date:	9/20/2016	
LSL ID #	> 003	Original Resi	Sample ults:	0.020	
Remediation Plan for Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results Afte	er Remediation:		Date:		
Site ID / Location of Sample:	2nd Floor Boys Room	ı Left Sink	Date:	9/20/2016	
LSL ID #	> 004	Original Resi	Sample ults:	0.0066	
Remediation Plan for Outlet / Tap: NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Girls Coach	Office	Date:	9/20/2016	
LSL ID # > 005 Original Sample Results:				0.0043	
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	2nd Floor Boys Roo	m Right Sink	Date:	9/20/2016	
LSL ID#	> 006	Original	Sample	0.0039	
Remediation Plan f	or Outlet / Tap:	Resi	ults:		
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Boys Restroom Right Hallway	Sink Gym	Date:	9/20/2016		
or sample.	Hallway					
LSL ID#	> 007	Original	Sample	0.013		
'	Results:					
Remediation Plan f	Remediation Plan for Outlet / Tap:					
	ESSARY					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 121 Four	ntain	Date:	9/20/2016		
LSL ID#	> 008	Original	Sample	0.0014		
Remediation Plan f	ults:					
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	2nd Floor Fountain Room	at Server	Date:	9/20/2016	
·	> 009	Original	Camarala	0.0000	
LSL ID #	0.0098				
		Resi	ults:		
Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 121 Si	nk	Date:	9/20/2016	
LSL ID#	> 010	Original	Sample	0.0057	
		Resi	•		
Remediation Plan f	or Outlet / Tap:				
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	Sample Results After Remediation: N/A Date:				

Site ID / Location of Sample:	Gym Hallway Girl Right Si		Date:	9/20/2016	
LSL ID # >011 Original Sample Results:			0.011		
Remediation Plan f					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Girls Locker Roo	m Fountain	Date:	9/20/2016	
LSL ID#	> 012	Original	Sample	0.0083	
Results: Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	Sample Results After Remediation: N/A Date:			

Site ID / Location	Boys Restroom Le	•	Date:	9/20/2016		
of Sample:	Hallwa	у		3, 23, 2020		
LSL ID # > 013 Original Sample Results:				0.0093		
Remediation Plan f	Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Art Room Rig	tht Sink	Date:	9/20/2016		
LSL ID #	> 014	Original	Sample	0.077		
Remediation Plan f	or Outlet / Tap:	Resi	ults:			
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
Sample Results After Remediation: Date:						

Site ID / Location of Sample:	Art Room Fro	ont Sink	Date:	9/20/2016	
LSL ID #	Sample ults:	0.0042			
Remediation Plan for Outlet / Tap: NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Principal Off	ice Sink	Date:	9/20/2016	
LSL ID#	> 0016	Original	•	0.064	
Remediation Plan f	or Outlet / Tap:	Resi	ults:		
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results After Remediation: Date:					

Site ID / Location of Sample:	Boys Locker Room F	ountain	Date:	9/20/2016	
LSL ID #	> 017	Original Res	Sample ults:	0.017	
Remediation Plan for Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results Afte	er Remediation:		Date:		
Site ID / Location of Sample:	Hall Fountain at Co	ncession	Date:	9/20/2016	
LSL ID #	> 018	Original Resi	Sample ults:	0.0010	
Remediation Plan f	or Outlet / Tap:				
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Concession Stan	d Left Sink	Date:	9/20/2016	
LSL ID # Remediation Plan f	0.0026				
Remediation Flam	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Girls Restroom Le Hallwa	•	Date:	9/20/2016	
LSL ID#	> 020	Original	Sample	0.0067	
Remediation Plan f	or Outlet / Tap:	Res	ults:		
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results After Remediation: N/A Date:				N/A	

Site ID / Location	1st Floor Boys Re	stroom Left	Date:	9/20/2016		
of Sample:	Sink		Date.	3/20/2010		
LSL ID#	> 021	Original	Sample	0.012		
		Resi	ults:			
Remediation Plan for Outlet / Tap:						
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Sink Nurse's	o Office	Date:	9/20/2016		
LSL ID#	> 022	Original	Sample	0.022		
·		Resi	ults:			
Remediation Plan f	or Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
Sample Results Afte	Sample Results After Remediation: Date:					

Site ID / Location of Sample:	Room 120 Fo	untain	Date:	9/20/2016		
LSL ID #	Sample ults:	0.0064				
Remediation Plan f	Remediation Plan for Outlet / Tap:					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Guidance Fo	untain	Date:	9/20/2016		
LSL ID #	> 024	Original	Sample	0.022		
Remediation Plan f	or Outlet / Tap:	Resi	ults:			
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
Sample Results Afte	er Remediation:		Date:			

Site ID / Location of Sample:	Concession Stand R	ight Sink	Date:	9/20/2016	
LSL ID #	> 025	Original Resi	• •	0.028	
Remediation Plan f					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results After Remediation: Date:					
Site ID / Location of Sample:	2nd Floor Girls Restr Sink	oom Left	Date:	9/20/2016	
LSL ID #	> 026	Original Resi	•	0.0061	
Remediation Plan f	or Outlet / Tap:				
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Art Room Left	Sink	Date:	9/20/2016	
LSL ID #	> 027	Original Resi	·	0.26	
Remediation Plan f	or Outlet / Tap:	ive 30	uits.		
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results Afte	er Remediation:		Date:		
Site ID / Location of Sample:	2nd Floor Girls Restro	oom Right	Date:	9/20/2016	
LSL ID # Remediation Plan f	> 028 For Outlet / Tap:	Original Resi		0.0079	
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	2nd Floor Faculty Restr	oom	Date:	9/20/2016
LSL ID #	> 029	_	Sample ults:	0.041
Remediation Plan for Outlet / Tap:				
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.				
Was Outlet / Tap Taken Out of Service: YES				
Sample Results Afte	er Remediation:		Date:	
Site ID / Location of Sample:	Conference Room		Date:	9/20/2016
LSL ID#	> 30	Original	Sample	0.016
Results: Remediation Plan for Outlet / Tap:				
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.				
Was Outlet / Tap Ta	aken Out of Service:	YES		
Sample Results Afte	er Remediation:		Date:	

Site ID / Location of Sample:	Gym Lobby Fo	ountain	Date:	9/20/2016	
LSL ID # > 031 Original Samp Results: Remediation Plan for Outlet / Tap:				0.0034	
Remediation Plan for Outlet / Tap:					
	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Kitchen Prep	Sink RT	Date:	9/20/2016	
LSL ID#	> 032	Original	Sample	0.16	
Remediation Plan f	or Outlet / Tap:	Resi	ults:		
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results Afte	Sample Results After Remediation: Date:				

Site ID / Location	1st Floor Girls Res	•	Date:	9/20/2016	
of Sample:	Sink		Date.	3/20/2010	
LSL ID #	> 033	Original Resi	-	0.012	
Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Superintendent	Office Sink	Date:	9/20/2016	
LSL ID #	> 034	Original	Sample	0.12	
Results: Remediation Plan for Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results After Remediation: Date:					

Site ID / Location of Sample:	Room 107 Foun	tain	Date:	9/20/2016	
LSL ID #	> 035	Original Resi	Sample	0.018	
Remediation Plan for Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results Afte	er Remediation:		Date:		
Site ID / Location	Business Office	Sink	Date:	9/20/2016	
of Sample:	Daomess office			3/20/2020	
LSL ID #	> 036	Original Res	Sample ults:	0.0042	
Remediation Plan f	or Outlet / Tap:				
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	1st Floor Faculty	Restroom	Date:	9/20/2016
LSL ID#	0.0055			
Remediation Plan f	ESSARY			
Was Outlet / Tap Taken Out of Service: NO				
Sample Results Afte	er Remediation:	N/A	Date:	N/A
Site ID / Location of Sample:	1st Floor Boys Res Sink	stroom Right	Date:	9/20/2016
LSL ID#	> 038	Original	Sample	0.0043
Results: Remediation Plan for Outlet / Tap:				
NO REMEDIATION NECESSARY				
Was Outlet / Tap Taken Out of Service: NO				
Sample Results After Remediation: N/A Date:				

Site ID / Location	1st Floor Girls Re	stroom Left	Date:	9/20/2016		
of Sample:	Sink					
LSL ID #	> 039	Original Resi	-	0.015		
Remediation Plan f	Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Music Room F	ountain	Date:	9/20/2016		
LSL ID #	> 040	Original	Sample	0.049		
Remediation Plan f	Results: Remediation Plan for Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
Sample Results Afte	Sample Results After Remediation: Date:					

Site ID / Location of Sample:	Room 114	Sink	Date:	9/20/2016	
LSL ID # > 041 Original Sample Results:				0.0078	
Remediation Plan for Outlet / Tap:					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 112 Rest	room Sink	Date:	9/20/2016	
LSL ID #	> 042	Original	Sample	0.047	
		Resi	ults:		
Remediation Plan f	•				
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Ta	aken Out of Service:	YES			
Sample Results Afto	Sample Results After Remediation: Date:				

Site ID / Location of Sample:	Room 114 Fo	ountain	Date:	9/20/2016	
LSL ID # > 043 Original Sample Results:				0.0015	
Remediation Plan for Outlet / Tap: NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Men's Facult	y Room	Date:	9/20/2016	
LSL ID#	> 044	Original	Sample	0.0026	
Remediation Plan f	or Outlet / Tap:	Resi	ults:		
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	Sample Results After Remediation: N/A Date:				

Site ID / Location of Sample:	Women's Facu	lty Room	Date:	9/20/2016	
LSL ID #	Sample ults:	0.0028			
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Kitchen Res	troom	Date:	9/20/2016	
LSL ID #	> 046	Original Resi	•	0.016	
Remediation Plan f	or Outlet / Tap:				
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.					
Was Outlet / Tap Taken Out of Service: YES					
Sample Results Afte	Sample Results After Remediation: Date:				

Site ID / Location of Sample:	Kitchen Prep	Left Sink	Date:	9/20/2016
LSL ID #	> 047	Original Resi	-	0.085
Remediation Plan f	or Outlet / Tap:			
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.				
Was Outlet / Tap Taken Out of Service: YES				
Sample Results Afte	er Remediation:		Date:	
Site ID / Location of Sample:	Kitchen Cent	ter Sink	Date:	9/20/2016
LSL ID #	> 048	Original	Sample	0.058
		Resi	ults:	
Remediation Plan f	or Outlet / Tap:			
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.				
Was Outlet / Tap Taken Out of Service: YES				
Sample Results Afte	er Remediation:		Date:	

Site ID / Location of Sample:	Room 112	Sink	Date:	9/20/2016		
LSL ID #	> 049	Original Resi	•	0.15		
Remediation Plan for Outlet / Tap: The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Ta	aken Out of Service:	YES				
Sample Results Afte	er Remediation:		Date:			
Site ID / Location of Sample:	Cafeteria Hall I	Restroom	Date:	9/20/2016		
LSL ID #	> 050	Original Resi	•	0.092		
Remediation Plan for Outlet / Tap: The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
Sample Results Afte	er Remediation:		Date:			

Site ID / Location of Sample:	Room 118 Four	ntain	Date:	9/20/2016		
LSL ID # > 051 Original Sample Results:			0.0028			
Remediation Plan f	ESSARY					
Was Outlet / Tap Ta	aken Out of Service:	NO				
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 117 Si	nk	Date:	9/20/2016		
LSL ID # Remediation Plan f	> 052 or Outlet / Tap:	Original Resu	•	0.0062		
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results After Remediation: N/A Date: N/A						

Site ID / Location of Sample:	Room 119 Si	nk	Date:	9/20/2016		
LSL ID #	> 053 Original Sampl Results:			0.0043		
Remediation Plan f	or Outlet / Tap:					
	NO REMED	DIATION NEC	ESSARY			
Was Outlet / Tap Ta	aken Out of Service:	NO				
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 118 Si	nk	Date:	9/20/2016		
LSL ID #	> 054	Original Resu	•	0.0063		
Remediation Plan for Outlet / Tap: NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results After Remediation: N/A Date:				N/A		

Site ID / Location of Sample:	Room 115 Fo	ountain	Date:	9/20/2016	
LSL ID # > 055 Original Sample Results: Remediation Plan for Outlet / Tap:			0.0033		
Remediation Flam	ESSARY				
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 116 Fo	ountain	Date:	9/20/2016	
LSL ID#	> 056	Original	Sample	0.0048	
Results: Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results After Remediation: N/A Date:				N/A	

Site ID / Location of Sample:	Room 120 Si	nk	Date:	9/20/2016			
LSL ID #	Results:			0.011			
Remediation Plan f	ESSARY						
Was Outlet / Tap Ta	aken Out of Service:	NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A			
Site ID / Location of Sample:	Room 115 Si	nk	Date:	9/20/2016			
LSL ID #	> 058	Original	•	0.0047			
Remediation Plan f	Results: Remediation Plan for Outlet / Tap:						
NO REMEDIATION NECESSARY							
Was Outlet / Tap Taken Out of Service: NO							
Sample Results After Remediation: N/A Date:				N/A			

Site ID / Location of Sample:	Room 114 Re	estroom	Date:	9/20/2016	
LSL ID # > 059 Original Sample Results: Remediation Plan for Outlet / Tap:			0.0087		
Nemedia ioni i iani	ESSARY				
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 116	Sink	Date:	9/20/2016	
LSL ID#	> 060	Original	Sample	0.0055	
Results: Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results After Remediation: N/A Date: N/A					

Site ID / Location of Sample:	Room 119 Fountain		Date:	9/20/2016		
LSL ID # > 061 Original Sample Results:			0.0048			
Remediation Plan f	ESSARY					
Was Outlet / Tap Ta	aken Out of Service:	NO				
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 117 Four	ntain	Date:	9/20/2016		
LSL ID # Remediation Plan f	> 062 or Outlet / Tap:	Original Resu	•	0.0035		
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	N/A					

Site ID / Location of Sample:	Concession Ice	Maker	Date:	9/22/2016		
LSL ID # > 001 Original Sample Results: Remediation Plan for Outlet / Tap:			0.0010			
Nemediation Flair	ESSARY					
Was Outlet / Tap Ta	aken Out of Service:	NO				
Sample Results Afte	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Kitchen Ice Ma	ıchine	Date:	9/22/2016		
LSL ID#	> 002	Original	Sample	0.0010		
Results: Remediation Plan for Outlet / Tap:						
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afte	er Remediation:	N/A	Date:	N/A		