#### Canaseraga Central School District Water Testing Results

#### **August 2019 Summary**

The information included in this report detail the laboratory results from water samples taken from locations in the school district building. Any sample results with a reading of greater than **0.015** signifies a lead content beyond the NYS approved limit for school districts.

The results contained in this report detail the actions taken by the district to address the higher than acceptable lead levels at particular locations in the building. Locations that had acceptable levels during the first testing are not reported here.

If you have any specific questions during the process, please don't hesitate to contact me directly. Thank you for your patience and understanding during the process.

Chad C. Groff
Superintendent of Schools
607-545-6421

Site ID / Location of Sample:	Rm 207 Front Sink		Date:	9/20/2016		
LSL ID #	> 002	Original Resi	Sample ults:	0.051		
Remediation Plan for Outlet / Tap:  The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.  Was Outlet / Tap Taken Out of Service: YES						
			Retest:	10/31/2016		
LSL ID #	> 004	Retest	Sample	0.0022		
Was Outlet / Tap Taken Out of Service: NO						
Comments:				_		
Location has been RESOLVED						

Site ID / L of San		2nd Floor Hallway Fountain		Date:	9/20/2016		
LSL I	D#	> 003	Original Resi	0.020			
Remediati	ion Plan f	or Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Taken Out of Service: YES							
NO Retesting Completed							
Comments:							

Fixture CLOSED and disconnected

Site ID / of Sar	Location mple:	Art Room Right Sink		Date:	9/20/2016		
LSL	ID#	> 014	> <b>014</b> Original Sample <b>0.077</b> Results:				
Remediation Plan for Outlet / Tap:							
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Taken Out of Service: YES							
NO Retesting Completed							
Comments:							
NO Drinking sign posted in location.							

Site ID / Location of Sample:	Principal Office Sink		Date:	9/20/2016
LSL ID #	> 0016	Original	Sample	0.064
omodiation Plan f	or Outlet / Tan:	Resi	ults:	

Remediation Plan for Outlet / Tap:

The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.

Was Outlet / Tap Taken Out of Service:

YES

**NO Retesting Completed** 

Comments:

Students do not have access to location.

NO Drinking sign posted in location.

Site ID / Location of Sample:	Boys Locker Room Fountain		Date:	9/20/2016				
LSL ID #	> 017	Original Sample 0.  Results:		0.017				
Remediation Plan	for Outlet / Tap:							
	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap	Taken Out of Service:	YES						
NO Retesting Com	pleted							
Comments:								

Fixture CLOSED and disconnected

Site ID / I of Sar		Sink Nurse's Office		Date:	9/20/2016			
LSL I	D#	> 022	Original Resi	•	0.022			
Remediat	ion Plan f	or Outlet / Tap:						
	The District will perform diagnostics on the outlet and the supply							
	plumbing to determine the origin of the contaminant, and sample after							
		the rem	ediation is con	nplete.				
Was Outlet / Tap Taken Out of Service: YES								
NO Retest	ting Comp	pleted						

NO Drinking sign posted in location.

Alternate water cooler available in office.

Comments:

Site ID / Location of Sample:	Guidance Fountain		Date:	9/20/2016				
LSL ID #	> 024	Original Resi	0.022					
Remediation Plan	for Outlet / Tap:							
	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Taken Out of Service: YES								
NO Retesting Completed								
Comments:								

Fixture CLOSED and disconnected

Site ID / Loca of Sample		Concession Stand Right Sink		Date:	9/20/2016		
LSL ID #		> 025	Original Sample Results:		0.028		
Remediation	Plan f	or Outlet / Tap:					
plu	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet /	Тар Та	aken Out of Service:	YES				
NO Retesting Completed							
Comments:	Comments:						

Fixture CLOSED and disconnected

Site ID / Lo of Samp		Art Room Left Sink		Date:	9/20/2016		
LSL ID	#	> 027	•	Original Sample 0.26			
Remediatio	Results: mediation Plan for Outlet / Tap:						
	The D	istrict will perform d	liagnostics on t	the outlet	and the supply		
p	plumbing to determine the origin of the contaminant, and sample after						
		the rem	ediation is con	nplete.			
Was Outlet	/ Tap Ta	aken Out of Service:	YES				
NO Retestir	ng Comp	oleted					
Comments:							
	٨	IO Drinking s	ign poste	d in lo	cation.		

Site ID / Loca of Sample		2nd Floor Faculty Restroom		Date:	9/20/2016			
LSL ID #	ł	> 029	Original Resi	•	0.041			
Remediation	Plan f	or Outlet / Tap:						
	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.  Was Outlet / Tap Taken Out of Service: YES							
NO Retesting	Comp	oleted						
Comments:								

Students do not have access to location.

NO Drinking sign posted in location.

Site ID / Lo of Samp		Conference Room		Date:	9/20/2016		
LSL ID	#	> 30	Original Sample 0.016				
Remediatio	Results: mediation Plan for Outlet / Tap:						
Г	The D	istrict will perform d	iagnostics on t	the outlet	and the supply		
p	plumbing to determine the origin of the contaminant, and sample after						
		the rem	ediation is con	nplete.			
Was Outlet	/ Tap Ta	aken Out of Service:	YES				
NO Retestin	ng Comp	oleted					
Comments:							
	٨	IO Drinking s	ign poste	d in lo	cation.		

Site ID / Location of Sample:	Kitchen Prep	Sink RT	Date:	9/20/2016		
LSL ID #	> 032	Original Resu	- 1	0.16		
Remediation Plan for Outlet / Tap:  The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Taken Out of Service: YES						
			Retest:	4/15/2018		
LSL ID #	> 001	Retest	Sample	0.0059		
Was Outlet / Tap Taken Out of Service: NO						
Comments:						
Location has been RESOLVED						

Site ID / Lo		Superintendent Office Sink		Date:	9/20/2016			
LSL ID #		> 034	Original Sample [ Results:		0.12			
Remediation	on Plan f	or Outlet / Tap:	il Co	uits.				
,	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Taken Out of Service: YES								
NO Retesti	ng Comp	pleted						
Comments:								

Students do not have access to location.

NO Drinking sign posted in location.

Site ID / Location of Sample:	Room 107 Fountain		Date:	9/20/2016
LSL ID #	> 035	Original	Sample	0.018
•		Resi	ults:	

Remediation Plan for Outlet / Tap:

The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.

Was Outlet / Tap Taken Out of Service:

YES

**NO Retesting Completed** 

Comments:

NEW Bottle Fill Cooler Installed.
Location has been RESOLVED

Site ID / Lo		Music Hallway Fountain		Date:	9/20/2016		
LSL ID	#	> 040	Original Resi	Sample ults:	0.049		
Remediation	n Plan f	or Outlet / Tap:					
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Taken Out of Service: YES							
NO Retesting Completed							
Comments:							

Fixture CLOSED and disconnected

Site ID / Location of Sample:	Room 112 Rest	room Sink	Date:	9/20/2016			
LSL ID #	> 042	Original Sample Results:		0.047			
Remediation Plan f	or Outlet / Tap:						
	District will perform o	_					
plumbing	g to determine the o	rigin of the cor nediation is con		, and sample after			
Was Outlet / Tap Taken Out of Service: YES							
			Retest:	8/19/2019			
LSL ID #	> 002	Retest	Sample	0.0084			
Was Outlet / Tap Taken Out of Service: NO							
Comments:							
Location has been RESOLVED							

Site ID / of Sar		Kitchen Res	Kitchen Restroom		9/20/2016			
LSL ID #		> 046	Original Sample 0.016 Results:		0.016			
Remediat	ion Plan f	or Outlet / Tap:						
Was Outle	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.  et / Tap Taken Out of Service: YES							
NO Retesting Completed								

Students do not have access to location.

NO Drinking sign posted in location.

Comments:

Site ID / Location of Sample:	Kitchen Prep L	eft Sink	Date:	9/20/2016				
LSL ID #	> 047	Original Resu	•	0.085				
Remediation Plan for Outlet / Tap:  The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after								
Was Outlet / Tap Taken Out of Service: YES								
	Retest: <b>4/12/2018</b>							
LSL ID #	> 002	Retest	Sample	0.0036				
Was Outlet / Tap Taken Out of Service: NO								
Comments:								
Location has been RESOLVED								

Site ID / Location of Sample:	Kitchen Center Sink		Date:	9/20/2016			
LSL ID #	> <b>048</b> Original Sample <b>0.058</b> Results:						
Remediation Plan for Outlet / Tap:  The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Ta	aken Out of Service:	YES					
			Retest:	10/31/2016			
LSL ID #	> 002	Retest	Sample	0.0013			
Was Outlet / Tap Taken Out of Service: NO							
Comments:							
Location has been RESOLVED							

Site ID / Location of Sample:	Room 112	! Sink	Date:	9/20/2016		
LSL ID #	> 049	_	Sample ults:	0.15		
Remediation Plan f	or Outlet / Tap:	Kes	uits:			
The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.						
Was Outlet / Tap Ta	aken Out of Service:	YES				
			Retest:	8/19/2019		
LSL ID #	> 003	Retest	Sample	0.095		
Was Outlet / Tap Taken Out of Service: NO						
Comments:						
NO Drinking sign posted in location.						

Site ID / Location of Sample:	Cafeteria Hall I	Restroom	Date:	9/20/2016				
LSL ID #	> <b>050</b> Original Sample <b>0.092</b> Results:							
Remediation Plan f				1.1				
	The District will perform diagnostics on the outlet and the supply plumbing to determine the origin of the contaminant, and sample after the remediation is complete.							
Was Outlet / Tap Taken Out of Service: YES								
	Retest: <b>8/19/2019</b>							
LSL ID #	> 001	Retest	Sample	0.0078				
Was Outlet / Tap Taken Out of Service: NO								
Comments:								
Location has been RESOLVED								