The information included in this report detail the laboratory results from water samples taken from locations in the school district building. Any sample results with a reading of greater than **0.015** signifies a lead content beyond the NYS approved limit for school districts. We will be working to diagnose the problem areas and will be taking steps to replace piping and / or fixtures in the problem areas. In certain locations, we may only be able to post a NO Drinking sign.

If you have any specific questions during the process, please don't hesitate to contact me directly. Thank you for your patience and understanding during the process.

Chad C. Groff
Superintendent of Schools
607-545-6421

Site ID / Location of Sample:	Room 119 sir	nk	Date:	1/30/2020			
LSL ID #	0.001						
Remediation Plan f	Remediation Plan for Outlet / Tap:						
	NO REMED	IATION NEC	ESSARY				
Was Outlet / Tap Taken Out of Service: NO							
Sample Results Afto	er Remediation:	N/A	Date:	N/A			
Site ID / Location of Sample:	Server Roon	n	Date:	1/30/2020			
LSL ID #	> 002	Original	Sample	0.0087			
Remediation Plan f	or Outlet / Tap:	Resi	ults:				
NO REMEDIATION NECESSARY							
Was Outlet / Tap Taken Out of Service: NO							
Sample Results Afto	er Remediation:	N/A	Date:	N/A			

Site ID / Location of Sample:	2nd Floor Women's Right Sink		Date:	1/30/2020	
LSL ID #	0.001				
Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Women's Bathroom Left Sink	New Gym	Date:	1/30/2020	
LSL ID #	> 004	Original -	•	0.0016	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service:  NO  Sample Results After Remediation:  N/A  Date:  N/A					
Sample Results Afte	ample Results After Remediation: N/A Date:				

Site ID / Location of Sample:	2nd Floor Women's Left Sink		Date:	1/30/2020	
LSL ID #	> 005	Original Resu	•	0.001	
Remediation Plan f	ESSARY				
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	2nd Floor Men's Bat Sink	hroom Left	Date:	1/30/2020	
LSL ID #	> 006	Original	•	0.001	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
	NO KLIVILI	DIATION NEC	LSSANT		
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afte	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Faculty Men's Bat	hroom Sink	Date:	1/30/2020
LSL ID #	> 007	Original Resi	Sample ults:	0.0069
Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY				
Was Outlet / Tap Taken Out of Service: NO				
Sample Results Aft	er Remediation:	N/A	Date:	N/A
Site ID / Location of Sample:	2nd Floor Fo	untain	Date:	1/30/2020
LSL ID #	> 008	•	Sample ults:	0.0023
Remediation Plan	for Outlet / Tap:	nesi	uits.	
NO REMEDIATION NECESSARY				
Was Outlet / Tap Taken Out of Service: NO				
Sample Results Aft	er Remediation:	N/A	Date:	N/A

Site ID / Location of Sample:	Faculty Women's Bath	room Sink	Date:	1/30/2020	
LSL ID #	Sample ults:	0.0087			
Remediation Plan 1	or Outlet / Tap:				
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Aft	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Conference Room	ı Sink	Date:	1/30/2020	
LSL ID #	> 010	Original Resi	•	0.022	
Remediation Plan for Outlet / Tap:					
NO Drinking sign posted in location.					

Site ID / Location of Sample:	Elementary Hallway	Fountain	Date:	1/30/2020		
LSL ID #	> 011	Original Resi	•	0.001		
Remediation Plan f	ESSARY					
Was Outlet / Tap Ta	Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Kitchen Prep Sink	ς Right	Date:	1/30/2020		
LSL ID#	> 012	Original	•	0.001		
Remediation Plan f	or Outlet / Tap:	Resi	uits:			
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	Room 118 Sir	nk	Date:	1/30/2020	
LSL ID #	0.0019				
Remediation Plan f	ESSARY				
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 120 Sir	nk	Date:	1/30/2020	
LSL ID #	> 014	Original	•	0.0014	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Room 114 Fou	untain	Date:	1/30/2020	
LSL ID #	0.001				
Remediation Plan f	ESSARY				
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Kitchen Prep Si	ink Left	Date:	1/30/2020	
LSL ID #	> 016	Original Resu	•	0.001	
Remediation Plan f	or Outlet / Tap:	nesi			
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Cafeteria Ice Ma	nchine	Date:	1/30/2020	
LSL ID #	0.001				
Remediation Plan f	ESSARY				
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 119 Fou	ntain	Date:	1/30/2020	
LSL ID #	> 018	Original	•	0.0014	
Results: Remediation Plan for Outlet / Tap:					
	NO REMEL	PIATION NEC	ESSAKY		
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Room 114 Sir	nk	Date:	1/30/2020	
LSL ID #	0.0016				
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 207 Left	Sink	Date:	1/30/2020	
LSL ID#	> 020	Original	•	0.0035	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Principal's Office	Sink	Date:	1/30/2020	
LSL ID #	0.0031				
Remediation Plan f	ESSARY				
Was Outlet / Tap T	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 120 Foun	tain	Date:	1/30/2020	
LSL ID #	> 022	Original	•	0.001	
Results: Remediation Plan for Outlet / Tap:					
	NO REMEDI.	ATION NEC	ESSARY		
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Band Room S	ink	Date:	1/30/2020	
LSL ID # > 023 Original Samp Results:				0.013	
Remediation Plan f					
Was Outlet / Tap T					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Art Room (single	e sink)	Date:	1/30/2020	
LSL ID #	> 024	Original	•	0.0014	
Remediation Plan f	or Outlet / Tap:	Resi	uits:		
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Men's Bathroom by N Right Sink		Date:	1/30/2020		
LSL ID #	> 025	Original Resu	•	0.0013		
Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY						
Was Outlet / Tap Ta	Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 118 Four	ntain	Date:	1/30/2020		
LSL ID#	> 026	Original	•	0.0018		
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	Room 115 Fou	ntain	Date:	1/30/2020		
LSL ID #	0.001					
Remediation Plan f	Remediation Plan for Outlet / Tap:					
	NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Women's Bathroom Office Right S	-	Date:	1/30/2020		
LSL ID #	> 028	Original	Sample	0.001		
Results:  Remediation Plan for Outlet / Tap:						
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	Men's Bathroom by N Left Sink	lain Office	Date:	1/30/2020	
LSL ID #	> 029	Original Resu	-	0.001	
Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 121 Four	ntain	Date:	1/30/2020	
LSL ID #	> 030	Original	•	0.001	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Room 112 Kitch	ien Sink	Date:	1/30/2020	
LSL ID #	> 031	Original Resi	-	0.023	
Remediation Plan f	or Outlet / Tap:				
٨	IO Drinking si	gn poste	d in lo	cation.	
Site ID / Location of Sample:	Men's Bathroom Ne Sink	ew Gym Left	Date:	1/30/2020	
LSL ID #	> 032	Original	-	0.0013	
Remediation Plan f	or Outlet / Tap:	Resi	uits:		
NO REMEDIATION NECESSARY					
Was Outlet / Tap Ta	aken Out of Service:	NO			
Sample Results Afte	er Remediation:	N/A	Date:	N/A	
			•		

Site ID / Location of Sample:	Kitchen Single S	Sink	Date:	1/30/2020	
LSL ID #	0.002				
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Women's Bathroom I Right Sink	New Gym	Date:	1/30/2020	
LSL ID#	> 034	Original	•	0.0024	
Results: Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Women's Bathroon Office Left Si	•	Date:	1/30/2020		
LSL ID # Remediation Plan f	> <b>035</b>	Original Resi	Sample ults:	0.001		
Nemediation Flam	ESSARY					
Was Outlet / Tap Ta	Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	5th Grade Fou	ntain	Date:	1/30/2020		
LSL ID #	> 036	Original Resi	•	0.001		
Remediation Plan f	or Outlet / Tap:	resi	uits.			
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	Room 207 Right	Sink	Date:	1/30/2020	
LSL ID #	0.0025				
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Concession Ice M	achine	Date:	1/30/2020	
LSL ID #	> 038	Original	•	0.001	
Results: Remediation Plan for Outlet / Tap:					
NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	2nd Floor Men's Bath Sink	room Right	Date:	1/30/2020	
LSL ID #	> 039	Original Resu	•	0.001	
Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Aft	er Remediation:	N/A	Date:	N/A	
			1		
Site ID / Location of Sample:	Art Room Right	: Sink	Date:	1/30/2020	
LSL ID #	> 040	Original Resu	•	0.017	
Remediation Plan for Outlet / Tap:  Some sections of piping changed					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Aft	er Remediation:	0.012	Date:	6/11/2020	

Site ID / Location of Sample:	Room 121 Si	nk	Date:	1/30/2020	
LSL ID #	0.001				
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Staff Bathroom	Sink	Date:	1/30/2020	
LSL ID #	> 042	Original	•	0.001	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Room 112 Bathroo	om Sink	Date:	1/30/2020		
LSL ID #	0.0089					
Remediation Plan f	ESSARY					
Was Outlet / Tap Ta	Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 115 Si	nk	Date:	1/30/2020		
LSL ID#	> 044	Original	•	0.001		
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	Kitchen Bathroo	m Sink	Date:	1/30/2020	
LSL ID #	0.0017				
Remediation Plan f	ESSARY				
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	
Site ID / Location of Sample:	Room 116 Four	ntain	Date:	1/30/2020	
LSL ID #	> 046	Original	•	0.001	
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A	

Site ID / Location of Sample:	Unisex Bathroom A Cafeteria		Date:	1/30/2020		
LSL ID #	0.015					
Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY						
Was Outlet / Tap Ta	Was Outlet / Tap Taken Out of Service: NO					
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample: Room 116 Sink Date:				1/30/2020		
LSL ID#	> 048	Original	•	0.001		
Results: Remediation Plan for Outlet / Tap:						
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		

Site ID / Location of Sample:	Art Room Lef	t Sink	Date:	1/30/2020	
LSL ID #	LSL ID # > <b>049</b> Original Sample Results:				
Remediation Plan f	or Outlet / Tap:				
٨	IO Drinking si	gn poste	d in lo	cation.	
Cita ID / Lagation			l 1		
Site ID / Location of Sample:	Concession	Sink	Date:	1/30/2020	
LSL ID #	> 050	Original	Sample	0.0039	
Results:					
Remediation Plan f	or Outlet / Tap:				
	NO REME	DIATION NEC	ESSARY		
Was Outlet / Tap T	aken Out of Service:	NO			
Sample Results Aft	er Remediation:	N/A	Date:	N/A	
		/		, : :	

Site ID / Location of Sample:	Men's Locker Room	Fountain	Date:	1/30/2020		
LSL ID # > <b>051</b> Original Sample Results:			•	0.001		
Remediation Plan f	ESSARY					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	Date:	N/A				
Site ID / Location of Sample:	Women's Locker Roo	m Fountain	Date:	1/30/2020		
LSL ID #	> 052	Original Resi	•	0.0028		
Remediation Plan for Outlet / Tap:						
NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results After Remediation: N/A Date:				N/A		

Site ID / Location of Sample:	Room 117 Si	nk	Date:	1/30/2020		
LSL ID # > <b>053</b> Original Sample Results:			•	0.001		
Remediation Plan f	ESSARY					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Main Office Fou	ntain	Date:	1/30/2020		
LSL ID # > <b>054</b> Original Sample				0.001		
Results: Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service: NO						
Sample Results After Remediation: N/A Date:				N/A		

Site ID / Location of Sample:	Coach Office Sink		Coach Office Sink Date		Date:	1/30/2020
LSL ID # > 055 Original Sample Results:			-	0.001		
Remediation Plan f	ESSARY					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A		
Site ID / Location of Sample:	Room 117 Foun	tain	Date:	1/30/2020		
LSL ID # > 056 Original Sample				0.001		
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY						
Was Outlet / Tap Taken Out of Service:  NO  Sample Results After Remediation:  N/A  Date:  N/A						
Sample Results Alto	IV / A					

Site ID / Location of Sample:	Room 114 Restro	om Sink	Date:	1/30/2020			
LSL ID # > 057 Original Sample Results:				0.001			
Remediation Plan f	ESSARY						
Was Outlet / Tap Ta	Was Outlet / Tap Taken Out of Service: NO						
Sample Results Afto	er Remediation:	N/A	Date:	N/A			
Site ID / Location of Sample:	Nurse's Office	Sink	Date:	1/30/2020			
LSL ID # > <b>058</b> Original Sample				0.0063			
Results:  Remediation Plan for Outlet / Tap:  NO REMEDIATION NECESSARY							
Was Outlet / Tap Taken Out of Service: NO							
Sample Results After Remediation: N/A Date:				N/A			

Site ID / Loca of Sample		Men's Bathroom N Right Sink	•	Date:	1/30/2020	
LSL ID #	:	> <b>059</b> Original Sam Results:		•	0.0012	
Remediation Plan for Outlet / Tap:						
	NO REMEDIATION NECESSARY					
Was Outlet / Tap Taken Out of Service: NO						
Sample Results After Remediation: N/A Date: N/A					N/A	